

---

Subject: kilomax 18 making noise

Posted by [bqc](#) on Fri, 26 Jul 2002 01:00:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I am using a kilomax 18" in a 12.5 cuft box tuned to 25hZ. I hooked it up to an amp driven by a PC program that generate sinewaves via a sound card. At low volume and at around 25 hZ, I heard some noise coming from the voice coil intermittently, sounds like the coil is rubbing or something. This is a brand newpart. Could it be a defect? or is the Kilomax 18 known to do thisat this frequency due to the use of the external heat sink for the voice coil?

---