

---

Subject: Did we forget to include duct material in your kits?

Posted by [Wayne Parham](#) on Wed, 18 Sep 2002 19:07:05 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The port is spec'ed at 2.0" O.D. with 0.030" wall thickness for an inside diameter of 1.94". Did we send you the port material? Because if we did, you'll want to drill to fit. Would it mess up the veneer to do that? If we forgot to send the port, let me know and we'll send it right away.