
Subject: Hi Gang

Posted by [Art J.](#) on Sat, 19 Oct 2002 00:47:17 GMT

[View Forum Message](#) <> [Reply to Message](#)

Here is the article from the 60's that you may have seen. This is what got me going back then. I guess I'm getting old. You see; large ports need a large box. The ideal back then was to have the port area the same as the cone area and tune by box volume. The port then becomes an effective radiator. The box is very large.....

<http://www.lansingheritage.org/html/altec/plans/1960s-plans.htm>