Subject: New specs on eminence drivers
Posted by Wayne Parham on Mon, 11 Nov 2002 17:45:21 GMT
View Forum Message <> Reply to Message

You're right, Eminence has changed their specifications. They've procured more accurate measurement systems and they've updated their data. They've built a new measurement chamber and installed a Klippel measurement system, which is the best in the industry. Eminence has also changed their drivers, so it isn't just the measurements that are different. They have maintained compatibility with earlier models, but they have made improvements that increase power handling. The voice coil manufacturing process has been changed, and so the new drivers

difficult part is knowing which particular motor you have, since there is no part number change to identify it. I think it's a safe assumption that if it has the old label and spec sheet, then it's the old part.