

---

Subject: Re: Theater 4's w/ EL-84 at 14 Watts per  
Posted by [Scholl](#) on Fri, 06 Dec 2002 20:46:52 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Maybe a flakey 7199 connection or tube. Before turn on next time reseal them several times. Also maybe a flakey carbon resistor most likely in the screen grid circuit of the 7199.

---