

---

Subject: Re: Coils, sawdust and stuffing

Posted by [Wayne Parham](#) on Tue, 22 Apr 2003 12:08:17 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I like R11 and R13 insulation best, so you might give that a go. And you might also want to install a 0.5mH coil in series with the Alpha 10.

---