

---

Subject: Re: Fin cutting - Just the welds!

Posted by [tdc](#) on Thu, 08 May 2003 17:38:29 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I did all the steps more or less at once. I did not conduct extensive listing test with each step progress. There is some improvement but its not like going from a bad crossover to a perfect one. When you strike the horn after all the above is done there is a dull lower thud and you know its dampened. You could also use the horn to make a cast and then pour the cast with depleted uranium from surplus operation Iraqi Freedom shells. Now that would be dead. tdc

---