Subject: Re: Top octave super tweeters Posted by Wayne Parham on Thu, 24 Jul 2003 15:13:35 GMT View Forum Message <> Reply to Message

You'll probably blow the tweeter at very low power levels (like under 10 watts) if you remove the coil. I'm confident you've correctly identified that as a shunt coil forming a second-order high pass filter. Same thing with the crossover point - It probably can't be pushed any lower without damage to the tweeter.