

---

Subject: Formula's

Posted by [Adrian Mack](#) on Sat, 14 Feb 2004 00:33:56 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Does anyone have formula's to calculate the new value of Qts/Qms/Qes/Fs as you add more mass to the cone? I have some formulas here, but they are dependant on each other, so it doesn't work right for this. As you can see:Qms there relies on Rms as well, and to calculate Rms requires Qms. + I think Rms relies on Mms, as its related to Qms. Any help highly appreciated!Adrian

---