Subject: Re: Wayne, what are you up to with the mag12? Posted by Bill Wassilak on Mon, 05 Apr 2004 17:50:13 GMT View Forum Message <> Reply to Message

Won't work because the sensitivity of the driver's to low. The more xmax a driver has the lower the sensitivity, and with a strong magnet to control the cone as in the MAG12 the better they are for driving a horn.Bill W.

