

---

Subject: Re: Wayne, what are you up to with the mag12?  
Posted by [Bill Wassilak](#) on Mon, 05 Apr 2004 17:50:13 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Won't work because the sensitivity of the driver's is too low. The more xmax a driver has the lower the sensitivity, and with a strong magnet to control the cone as in the MAG12 the better they are for driving a horn. Bill W.

---