

---

Subject: Re: Implementation

Posted by [Adrian Mack](#) on Fri, 16 Apr 2004 23:30:42 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Good idea. So its the same gasket thats on the driver, having essentially two of them? How thick are the gaskets/spacer on the Alpha 10 by the way?

---