
Subject: Crap bought a bunch of worthless crossover parts
Posted by [James W. Johnson](#) on Sat, 17 Jul 2004 02:19:49 GMT
[View Forum Message](#) <> [Reply to Message](#)

I thought I needed 10 8 ohm 10 watt resistors to make an 8ohm 100watt part...I used the same thinking for all of them. :(these Eagle resistors were a buck each...what a waste.What in the heck do I really need here, I am having trouble with the math here.thanks
