

---

Subject: Re: Obviously, I stand corrected...

Posted by [Larry Acklin](#) on Mon, 19 Jul 2004 15:43:19 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I'm coming in late to this discussion. 2 ea 8 ohm in series = 16 ohm  
2 of those series assemblies in parallel = 8 ohms  
4 of the series assemblies in parallel = 4 ohms. That's too low, right? Larry Acklin

---