

---

Subject: Re: drop in replacements?

Posted by [James W. Johnson](#) on Thu, 29 Jul 2004 13:19:20 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Wayne, So are the following CTS drivers basically the same.. 1038,1041,1056 ?Are there any other drop in replacements for the One and Two Pis?

---