

---

Subject: I went back to the "right x-over" and lost something

Posted by [BillEpstein](#) on Sun, 10 Apr 2005 08:59:01 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Now running the 8 Ohm 902's with 4Pi Pro Eminence 1.6k extra cap on the woofer removed. The extra detail and most of the sparkle is still there but some of the ambience is lost. And the Marantz receiver became shrill; the Ella necessary for listening above moderate levels. Am I missing the 1200 Hz crossover point? The 16 ohm caps: 5.6 and 16? The 1.5mH 15 ga. foil coil?

---