

---

Subject: Re: BTW....

Posted by [Paul C.](#) on Thu, 15 Dec 2005 02:04:51 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Yes, they should cross over before that 2000 hz-2500 hump. But even with the crossover rolling them off, they still may have a high peak that interferes with getting an accurate xover. With some, even with 12 db/oct, this peak makes them unsuitable for the 1600 hz xover freq recommended for the Eminence PSD2002. A 2-way will not work for these, you would have to go much lower, and probably go to a 3-way system.

---