

---

Subject: 6pi

Posted by [Wayne Parham](#) on Wed, 04 Jan 2006 15:55:55 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

when the woofer alignment is slightly overdamped. It will be hard to do that with an Alpha 12 unless the cabinet is very large.

---