

---

Subject: Re: 2 pi and PiAlign program

Posted by [Wayne Parham](#) on Sun, 14 May 2006 17:50:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Eminence is constantly changing specs and that figure was for an earlier model with slightly different values. I've noticed most times when they do that the parameters are compatible, in that the new driver specs work well in a cabinet designed for an earlier model, not excessively underdamped or anything like that.

---