

---

Subject: Re: Power Transfer into Professional Pi7  
Posted by [TomM](#) on Sat, 17 Jun 2006 20:25:46 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

All is well again. I found the culprit to be a pair of cathode tubes in my preamp that had weakened. After I replaced these I have all the power, bass, and slam that 140wpc of tube power can dish out. Those Outlaw monos now sound anemic by comparison.

---