

---

Subject: Re: Frequency response slope question  
Posted by [GarMan](#) on Wed, 21 Jun 2006 22:36:32 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Garland. I read your first paragraph several times and wonder if it's not an issue with different compression rates between woofer and drivers. It sounds like the treble is hot as volume goes up. I've experienced the same thing with high volumes and wonder if the woofer is compressing before tweeter.

---