

---

Subject: Re: Heat exchanger effectiveness

Posted by [Wayne Parham](#) on Fri, 23 Jun 2006 15:08:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

They work very well, don't they? What do you think of the size of the vent on the new HL10's? I

the vent to 3/4", I was concerned about vent airspeed and pressure behind the cone. What have you found?

---