

---

Subject: Re: Goodmans Axiom 201

Posted by [Wayne Parham](#) on Fri, 30 Jun 2006 16:06:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

If you cannot obtain the data, you can measure the drivers using the procedure shown in the post called "T/S Measurements".

---