

---

Subject: Re: 4 Pi Cabinet

Posted by [Wayne Parham](#) on Wed, 12 Jul 2006 19:43:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Great point, Gar, nice catch. I was focused on the question about port placement, but you've brought up what's more important in this situation, which is the positions of the drivers in relation to each other. They should stay the same, as you've said. Baffle spacing, phase angles and time alignment, revisited

---