

---

Subject: Re: Pioneer RT - 909

Posted by [Minas](#) on Sat, 20 Dec 2008 19:19:05 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Dear Wayne, hello and thanks for the e-mail, this happened before and later it worked again! But this time it completely stopped!! No play and no recording, NO MOVE! And when I turn it on, I smell something like burning!!! Happy Holidays, Minas

---