

---

Subject: You've got mail!

Posted by [Wayne Parham](#) on Tue, 06 Mar 2007 18:38:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You've over-estimated the sensitivity of the tweeter horn. I suggest the 14dB compensation circuit, which you'll see in the charts on the crossover document.

---