

---

Subject: Re: Pro 4 + seven midhorn and tweeter  
Posted by [beto1](#) on Tue, 01 May 2007 23:23:04 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hi,yes, also I have used marine plywood. The only downside is the voids, as Wayne stated as a possible problem. If I can get a plywood with no voids in its veneers I will get it, but I don't believe that I can find here made in pine. Pine has more separate fibers, so is easy to chip, ergo we have voids. MDF, as I have noted is a very wood material with some limitations, moisture and poor mechanical to use with heavy drivers, but we can control this with some products and also we can use a plywood or a wood board for the front panel to fix the drivers, then we can do a sandwich to get an interior MDF layer (just a thought).I will check also for the CNC labor, but maybe will be sufficient with a router. Best regards

---