

---

Subject: With top and bottom transitions

Posted by [swett](#) on Sat, 12 May 2007 21:08:16 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Here is a measurement I did 20 degrees below the horn with 2" long top and bottom transitions at a 50 degree angle to the horn's axis. Not perfect, but still pretty respectable I felt. I'll post the same measurement without the transitions next.

---