

---

Subject: 12Pi dado dept

Posted by [Roland Gama](#) on Sat, 02 Feb 2008 09:58:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hello Wayne, The diagram and the web link says that the depth of the dado on the access panel should be 7/16 of an inch as the the aluminum disc is 1/4 inch thickness. Do you actually mean 5/16 inch depth of dado to make up for 1/16 inch gasket thickness??? Waiting for your help before I go with the router. Thanks: Roland.

---