Subject: Re: Comments on this low-efficiency 2-way? Posted by Kim Schultz on Wed, 11 Jun 2008 08:18:36 GMT View Forum Message <> Reply to Message

I would not crossover this high on a 10" inch woofer, there might be some nasty cone breakup modes up there. The tweeter is a 28mm dome with a resonans freq. of 700hz, so it should be safe to cross anywhere from around 1500-2000hz/24db, and up. The woofer response shows a rising response from 900-2300hz, so you might want to cross lower on the woofer, and use the natural rolloff combined with the crossover, to get the desired crossover point.

Page 1 of 1 ---- Generated from AudioRoundTable.com