

---

Subject: Re: 7 Pi bass cabinet

Posted by [Matts](#) on Wed, 25 Jun 2008 20:52:42 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Paul, So far, much of what you're experiencing seems to me to be normal for new speakers. I'd wait until you have 100 hours or so on them to tinker too much. Have you tried the 8-ohm taps? You'll be shocked at what the upgraded iron does over the whole freq spectrum. You may have room modes, etc. that do need correcting, but I'd wait until the speakers stabilize before going all out. If you upgrade caps to Auricaps or something, you go through it again... Wayne breaks his speakers in fast- with a zillion watt Crown or two. hahahaha.

---