
Subject: Re: Fried my SL1200
Posted by [dB](#) on Wed, 19 Aug 2009 08:36:22 GMT
[View Forum Message](#) <> [Reply to Message](#)

My guess, original (different) power plugs should never be changed. (in this case to bare wires, unless same voltage/freq.)
