

---

Subject: Re: Pioneer RT-909

Posted by [Wayne Parham](#) on Fri, 08 Jan 2010 20:11:32 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Mine was a "speed adjustment", but since they're DC motors, it may be the same thing your shop is talking about.

---