

---

Subject: philco 48-1253

Posted by [capbuster](#) on Sun, 02 May 2010 23:19:01 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have this set . It has that hum . Would it be okay just to change the electrolytic caps, and line caps leave the rest alone .

Works great just has that hum.

THANKS.CAPBUSTER

---