
Subject: Re: Update: Audio Note power transformer
Posted by [Frihed89](#) on Tue, 01 Jun 2010 08:50:45 GMT
[View Forum Message](#) <> [Reply to Message](#)

I see you traced this problem back to a resistor. I would add that the new AN copper foil caps make very good coupling caps in a wide range of equipment, but are pricey, although not like the Vcaps or AN silver foils. The new AN caps are no longer made by Jensen. However, Jensens new caps no longer leak and specs appear tighter. If you order AN caps, try and get them matched.
