

---

Subject: Re: 4Pi crossover issue

Posted by [Wayne Parham](#) on Fri, 11 Jun 2010 20:37:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Cold solder joints can do that. Usually, a bad connection causes symptoms just like you're thinking, a make or break deal. But cold solders are different. You can have a junction with resistance, not completely disconnected.

---