

---

Subject: Re: Edison type 7R

Posted by [Wayne Parham](#) on Tue, 22 Jun 2010 02:34:52 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Wow, that's cool! But I'll bet it's a booger to align.

What tubes are missing? I wonder if it has been completely rewired, maybe even made into a newer circuit type.

Once I had a Stewart Warner radio that had been rewired to make use of an alternate output tube. I'm sure a repair shop rewired it to make use of a tube they had in stock that had different pinouts.