

---

Subject: Re: Airline 62-2704 Need Help

Posted by [Wayne Parham](#) on Tue, 29 Jun 2010 20:43:58 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

In your first post, you said there were some disconnected wires. Have you tried to identify the wires and reconnect them? Should have a couple for antenna/ground, probably four for the speaker (voice coil +/- and field coil +/-) and then of course the power cord.

Does it power up? Do the filaments glow?

---