Subject: Re: philco 48-1253

Posted by Wayne Parham on Sat, 14 Aug 2010 04:47:40 GMT

View Forum Message <> Reply to Message

If the positive lead isn't connected, it isn't doing anything. You can remove it. I imagine it is a power supply cap that was replaced at one point, but left in place for whatever reason.