

---

Subject: Re: Zenith Transoceanic G500 restoration  
Posted by [Wayne Parham](#) on Mon, 23 Aug 2010 14:33:41 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Are you sure those green devices are in the circuit positions where you would expect capacitors to be? I ask because they look like resistors to me. I also seem to recall my Transoceanics have one or two small value inductors that look kind of like resistors. So I would definitely double-check those parts by their position in the schematic, because I don't think they're capacitors.

---