

---

Posted by [Wayne Parham](#) on Mon, 11 Oct 2010 01:44:53 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I don't know, but the insulation and its position are pretty important. For example, if you don't span the cross-section with a sheet placed on the brace between the woofer and tweeter, you'll notice a blip in the lower midrange. So don't experiment with the insulation unless you know it is equivalent or you have some measurement gear to check it out.

---