

---

Subject: Re: Pi4 New Owner

Posted by [Doc Jr 8156](#) on Mon, 08 Nov 2010 22:43:48 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks Wayne. My problem is that the only way o access the cabinet is through the drivers. There is no opening at the back of the cabinet, except for the recess containing the binding post. Yes, I thought of solvents but it will make contact with the finish or be absorbed by the ply.

My other drastic solution would be to get another set of horns (H290?)and just drill holes on the installed one so I will have something to pull upon when removing the horn. Thanks again, Wayne.

Can youe-mail me the cabinet plan?

John Revilla

---