

---

Subject: Re: One more time

Posted by [Wayne Parham](#) on Tue, 16 Nov 2010 09:31:19 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

check internal standing wave modes. One of the most common problems I see with tower configurations is internal standing waves lining up in an unfavorable way and causing response anomalies. When you make a tower, the positions of woofer and port become somewhat critical. This is true for any large speaker with a midwoofer used through the midrange, but even more so with towers. There's more potential for unwanted standing wave problems. See the posts at the link below.

Internal Standing Waves

---