Subject: Re: Dynavector 10X5 Assist

Posted by gofar99 on Tue, 02 Aug 2011 01:12:15 GMT

View Forum Message <> Reply to Message

Hi Wayne, I considered that, but I'm concerned that it may be twisted as well and it will gouge the LPs. Soundsmith seems to be a good bet, but ouch, \$150 to replace the parts, 250 to upgrade to a ruby cantilever (original is aluminum). No lunch money for months.