

---

Subject: Re: IR Remote Control

Posted by [skywave-rider](#) on Sat, 16 Jun 2012 23:52:32 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Here's my BOM minus the PS stuff because I took a different approach. I am not sure if the caps in the IR rcvr circuit (1.0/.1uF) should be polarized electrolytic. Wayne?

I made my order at Mouser. Bill, I could not find the parts using the numbers you supplied for the gold sockets at Digikey. Could you verify those?

Relays:

- NEC EA2-12NJ (signal relay) x5

- Omron G4W-2214P-US-HP-DC12 (switched power relay) x1

- 220R x6

- 2N222 x6

IR Receiver:

- TSOP 4838

- 1.0uF

- .1uF

- 220R

Display (LED Meter):

- LM3916 x2

- 1.2KR x2

- 7.5KR x2

- 2.2uF tantalum x2

Momentary Switches:

- <http://www.parts-express.com/pe/showdetl.cfm?Partnumber=060-622> x6

---