

---

Subject: Re: 4Pi measurements

Posted by [Wayne Parham](#) on Sun, 04 Nov 2012 01:50:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

zheka wrote on Sat, 03 November 2012 15:26I finally had a chance to open the speaker with unhealthy boost in the crossover region - the zobel was disconnected! what a relief. I thought that was probably the cause. Glad you took the time to measure the speakers - It sure helped you nail it down!

---