

---

Subject: Re: Skywave's 3 Pi Build

Posted by [skywave-rider](#) on Sun, 17 Feb 2013 02:07:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks or pointing that out, Wayne. I did not consider that the voice coil former could be out of round, thinking there would be a tight tolerance in the gap. But now I understand that one is really the same as the other.

I am not talking about a diagonal. but out of round.

I think I can unscrew the phase plugs to get a better look at the vc former roundness.

Not happy at all.

---