

---

Subject: Re: Curcuit breaker going off on Yamaha RX-385

Posted by [chris](#) on Sun, 19 Jun 2005 00:14:36 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I think i found the problem. A speaker wire on my Bi wired AR-9's was lose and must have been shorting . Tightened it up and can now crank it again without it shutting down.

---