

---

Subject: Re: Buzzing Yamaha CA400

Posted by [Wayne Parham](#) on Tue, 13 Feb 2007 20:56:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I had an amp with a similar symptom once, and found that the potentiometer was broken. The substrate had cracked, probably in two places, making it partially open and intermittent. It was noisy when the knob was positioned within a range of medium positions.

---