

---

Subject: Re: 2Pi Help...

Posted by [Wayne Parham](#) on Mon, 19 May 2014 15:43:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I'd suggest either modeling the desired cabinet using Martin King's spreadsheet or building the box and measuring it to see if the midrange had any blips. Either way, you'll need to do some modeling and/or measurements.

---